



## Wiring the 1 Pole 12 Position Rotary Switch to a 2160 Board (J2 Connector)

### Wiring a 10 Position Mech. Rotary Switch to J2 Connector on the 2160 Board



**Not Used**



**2160 Board  
 Less Components**

Once wired, just program each position with the needed Flight Functions supported with either MS2002, MS2004, FSX, X-Plane and FSUIPC